

# AJA KONA, Io 4K, Io XT, Io Express, T-TAP Release Notes - Mac Driver v10.5.1

## Drivers for KONA, Io 4K, Io XT, Io Express and T-TAP™ on Mac OSX

### General

---

This driver version is compatible with Mac OSX 10.9 (Mavericks) and OS X 10.8 (Mountain Lion).


Please read the "ReadMeFirst.PDF" document, particularly if installing for the first time.

### Installation Notes—Please Read

---

#### Mac OS X Gatekeeper

On Mountain Lion and later versions of OSX, ensure that the Security & Privacy settings are configured to allow applications downloaded from Mac App Store and identified developers, as shown.



## New Features

---

### All

- Included additional formats in the AJA DataCalc desktop app
- Added support for progressive (p) vs. Psf selection in Control Panel

### lo 4K

- Added 50, 59.94, and 60 fps high frame rate capability at 4K (4096x2160) and UltraHD (3840x2160) resolutions

### lo XT

- Fixed the HDMI audio output 2/8 channel selector

## Relevant Products

---

The following products are covered by this update:

KONA 3G	lo 4K
KONA 3	lo Express
KONA LHi	lo XT
KONA LHe Plus	T-TAP™

## Version History

---

### 10.5 - Release Date: January 28, 2014

#### lo 4K

- Added support for lo 4K

### 10.4.9 - Release Date: November 6, 2013

#### All

- New Control Panel settings persistence model allows for customized 'house default' settings
- A/V sync fixes for VTR Xchange and FCP7 in Mavericks

### 10.4.8 - Release Date: October 24, 2013

#### All

- Added support for Mac OSX v10.9 (Mavericks)
- Increased minimum memory requirement to 8GB

## 10.4.7 - Release Date: August 27, 2013

### All

- Fixed a problem where the Control Panel application would crash when launched.

## 10.4.6 - Release Date: August 21, 2013

### All

- Fixed an issue where there were corrupted frames causing A/V sync problems during capture.

### KONA 3G

- Fixed an issue where the computer failed to restart after an install of the KONA driver

## 10.4.5 - Release Date: June 19, 2013

### Io XT

- Fixed issue where HDMI input was shifted to the right with 1080p50 input

### KONA 3G

- Fixed issue with no DSK output when DSK was enabled
- Fixed issue where embedded audio output had CRC errors
- Added support for the following formats:
  - 2Kp29.97, 2Kp30, 2Kp59.94, 2Kp60
  - QuadHDp29.97, QuadHDp30
  - 4Kp29.97, 4Kp30

### KONA LHe Plus

- Fixed issue with VANC data in 8-bit framebuffer mode

### All

- Fixed audio problem with repeated playback start/stop cycles in Apple Final Cut Pro 7