

# AJA KONA, Io and T-TAP Drivers

Release Notes - Mac Drivers v10.5.3

# General

This driver version is compatible with Mac OSX 10.9 (Mavericks) and OS X 10.8 (Mountain Lion).

# Installation Notes—Please Read

#### Mac OS X Gatekeeper

On Mountain Lion and later versions of OSX, ensure that the Security & Privacy settings are configured to allow applications downloaded from Mac App Store and identified developers, as shown.



# **Improvements**

lo 4K

- New Io 4K firmware
- Improves SDI output stability

# Relevant Products

The following products are covered by this update:

lo 4K

# Version History

### 10.5.2 - Release Date: April 24, 2014

All

 Fixed an issue where audio would continue playing back briefly after playback was stopped.

lo 4K

• Fixed an issue on VT/d-enabled MACs that could lock up the lo 4K until reset.

T-TAP

• Eliminated debug messages in the system log that were inadvertently introduced in 10.5.1.

# 10.5.1 - Release Date: February 19, 2014

All

- Included additional formats in the AJA DataCalc desktop app
- Added support for progressive (p) vs. PsF selection in Control Panel

lo 4K

 Added 50, 59.94, and 60 fps high frame rate capability at 4K (4096x2160) and UltraHD (3840x2160) resolutions

lo XT

• Fixed the HDMI audio output 2/8 channel selector

#### **10.5** - Release Date: January 28, 2014

lo 4K

• Added support for lo 4K

### **10.4.9** - Release Date: November 6, 2013

ΑII

- New Control Panel settings persistence model allows for customized 'house default' settings
- A/V sync fixes for VTR Xchange and FCP7 in Mavericks

## 10.4.8 - Release Date: October 24, 2013

ΑII

- Added support for Mac OSX v10.9 (Mavericks)
- Increased minimum memory requirement to 8GB

## **10.4.7** - Release Date: August 27, 2013

All

• Fixed a problem where the Control Panel application would crash when launched.

### 10.4.6 - Release Date: August 21, 2013

All

• Fixed an issue where there were corrupted frames causing A/V sync problems during capture.

KONA 3G

• Fixed an issue where the computer failed to restart after an install of the KONA driver

### 10.4.5 - Release Date: June 19, 2013

lo XT

• Fixed issue where HDMI input was shifted to the right with 1080p50 input

#### KONA 3G

- Fixed issue with no DSK output when DSK was enabled
- Fixed issue where embedded audio output had CRC errors
- Added support for the following formats:
  - 2Kp29.97, 2Kp30, 2Kp59.94, 2Kp60
  - QuadHDp29.97, QuadHDp30

• 4Kp29.97, 4Kp30

#### **KONA LHe Plus**

• Fixed issue with VANC data in 8-bit framebuffer mode

ΑII

 Fixed audio problem with repeated playback start/stop cycles in Apple Final Cut Pro 7

# **Technical Support**

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: <u>support@aja.com</u> Phone: +1-530-271-3190 Fax: +1-530-274-9442

Web: <a href="https://www.aja.com/support">www.aja.com/support</a> Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA